

VEHICLE INSPECTION REPORT

BN14WUY

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/03/2014

VIN ZCFA675B602623058

Gearbox MANUAL

Year 2014

Body Style Box Van

Axle Combi 4x2

Mileage 635,187 Km Warranted

Service history Yes

Rear Suspension Air

Fuel Type Diesel

Service documents Printout

Tail Lift Cantilever

Colour RED

MOT Due 31/07/2026

MILEAGE DISCRPENY ON MOT, COLLECTED AS NON-RUNNER, BRAKES REQ ATTN

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door nsf
 Scratched
 Over 25mm Thru Paint



4: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint




5: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



6: Qtr Panel osr
 Cracked
 Replace



7: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



8: Door osf
 Dented
 With Paint Damage





9: Screen Front
Chipped
Over 10mm

10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		