

VEHICLE INSPECTION REPORT

SA21ZZF

Fiat Doblo Work Up 1.6 Multijet II 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/05/2021

Year 2021

Mileage 86,846 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006T93092

Body Style Dropside

MOT Due 09/04/2026

CAP Clean £5,600.00

CAP Average £5,075.00

CAP Below £4,275.00

Gearbox MANUAL

Gears 5

WARNING LIGHTS ON DASH AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare


Features

- Rear parking sensor
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace

2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Qtr Panel Trim ns
Scuffed
Over 25mm

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
With Paint Damage

8: B Post ns
Dented
Over 30mm



9: Qtr Panel nsr
Dented
Over 30mm

10: Wheel nsr
Dented
Over 30mm (Steel)



11: Lamp osr
Broken
Replace

12: B Post os
Scratched
Over 25mm Thru Paint



13: Sill os
Scratched
Over 25mm Thru Paint

14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Broken
Replace

16: Wing osf
Dented
With Paint Damage



17: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

18: Door Pad osf
Broken
Replace



19: Fascia Panel
Missing
Replace

20: Carpets Front
Holed
Over 3mm



21: Seat Base Cover osf
Torn
Over 3mm

22: Seat Back Cover osf
Holed
Over 3mm



23: Seat Base Cover nsf
Soiled
Heavy

24: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		